

HELP WANTED



**YOUR NEW EMPLOYEE
IS RIGHT HERE!**



**SIMPLE
NO PROGRAMMING 7-AXIS
CNC PACKAGE**



Scan here to learn more



TAKE DOWN YOUR HELP WANTED SIGNS

LIGHTS OUT OPERATIONS 24/7

★ MADE IN ★



★ AMERICA ★



OB7-Stretch



OB7



OB7-Max 8



OB7-Max 12

Axes	7	7	7	7
Payload	8.8 lbs/4 kg	11 lbs/5 kg	17.6 lbs/8 kg	26 lbs/12 kg
Reach	49"/1250 mm	39"/1000 mm	66"/1700 mm	51"/1300 mm
Safety	ISO 10218-1 Safety Compliant ISO 9409-1-50-4-M6 End of Arm Connection	ISO 10218-1 Safety Compliant ISO 9409-1-50-4-M6 End of Arm Connection	ISO 10218-1 Safety Compliant ISO 9409-1-50-4-M6 End of Arm Connection	ISO 10218-1 Safety Compliant ISO 9409-1-50-4-M6 End of Arm Connection
Speed (Max w/opt. Lidar Unit or Safety Gaurding)	80"/sec.	80"/sec.	80"/sec.	80"/sec.
Cost	\$35,900	\$35,900	\$46,900	\$46,900



All OB7 Products only require a **110-volt outlet**. Plug into any standard machine and begin teaching it the job you want it to do!

www.absolutemachine.com
Lorain, OH | Mason, OH | Livonia, MI

ABSOLUTE MACHINE TOOLS

